

Appendix 2-A

Example 2-2

For the “test” machine given in Chapter 1, simulate the induction machine start-up in MATLAB using the equations derived in this chapter from a completely powered down state with no external load connected to it. Plot rotor speed, electromagnetic torque, stator and rotor currents.

Solution:

The parameters of the “test” machine in Chapter 1 are as follows:

Power:	1.5 MW
Voltage:	690 V (L-L, rms)
Frequency:	60 Hz
Phases:	3
Number of Poles:	6
Full-Load Slip	1 %
Moment of Inertia	$70\text{ kg}\cdot\text{m}^2$

Per-Phase Circuit Parameters:

$$R_s = 0.002 \Omega$$

$$R_r = 0.0015 \Omega$$

$X_\ell \cap \Omega$

$X_\ell \quad 47\Omega$

$$X_m = 0.86 \Omega$$

The stator and rotor flux vector λ can be written in terms of stator and rotor current vector i and the inductance matrix \mathbf{L} as

$$\lambda = \mathbf{L}\mathbf{I} \quad (1)$$

The vector λ can be written as

$$\lambda = \begin{bmatrix} \lambda_a \\ \lambda_b \\ \lambda_c \\ \lambda_A \\ \lambda_B \\ \lambda_C \end{bmatrix} \quad (2)$$

where λ_x , [x=a,b,c] denotes the flux of stator phases, while λ_X , [X=A,B,C] denotes the fluxes of rotor phases. Applying the same notations to the currents vector

$$\mathbf{I} = \begin{bmatrix} i_a \\ i_b \\ i_c \\ i_A \\ i_B \\ i_C \end{bmatrix} \quad (3)$$

The inductance matrix \mathbf{L} is given as follows:

$$\mathbf{L} = L_{m,1\text{-phase}} \begin{bmatrix} 1+k_{ls} & \cos(\alpha) & \cos(2\alpha) & \cos(\theta_m) & \cos(\theta_m + \alpha) & \cos(\theta_m + 2\alpha) \\ \cos(2\alpha) & 1+k_{ls} & \cos(\alpha) & \cos(\theta_m + 2\alpha) & \cos(\theta_m) & \cos(\theta_m + \alpha) \\ \cos(\alpha) & \cos(2\alpha) & 1+k_{ls} & \cos(\theta_m + \alpha) & \cos(\theta_m + 2\alpha) & \cos(\theta_m) \\ \cos(\theta_m) & \cos(\theta_m + 2\alpha) & \cos(\theta_m + \alpha) & 1+k_{lr} & \cos(\alpha) & \cos(2\alpha) \\ \cos(\theta_m + \alpha) & \cos(\theta_m) & \cos(\theta_m + 2\alpha) & \cos(2\alpha) & 1+k_{lr} & \cos(\alpha) \\ \cos(\theta_m + 2\alpha) & \cos(\theta_m + \alpha) & \cos(\theta_m) & \cos(\alpha) & \cos(2\alpha) & 1+k_{lr} \end{bmatrix} \quad (4)$$

where

$L_{m,1\text{-phase}}$ = per phase magnetizing inductance of the induction machine,

θ_m = electrical angle between the stator a-axis and rotor A-axis,

k_{ls} = ratio of L_{ls} (stator leakage inductance) and $L_{m,1\text{-phase}}$,

k_{lr} = ratio of L_{lr} (rotor leakage inductance) and $L_{m,1\text{-phase}}$, and

$$\alpha = \frac{2\pi}{3}$$

The voltage current equations can be written in vector form as

$$\mathbf{V} = \frac{d\boldsymbol{\lambda}}{dt} + \mathbf{R}\mathbf{I} \quad (5)$$

where

$$\mathbf{V} = \begin{bmatrix} v_a \\ v_b \\ v_c \\ v_A \\ v_B \\ v_C \end{bmatrix} \quad (6)$$

and,

$$\mathbf{R} = \begin{bmatrix} R_s & 0 & 0 & 0 & 0 & 0 \\ 0 & R_s & 0 & 0 & 0 & 0 \\ 0 & 0 & R_s & 0 & 0 & 0 \\ 0 & 0 & 0 & R_r & 0 & 0 \\ 0 & 0 & 0 & 0 & R_r & 0 \\ 0 & 0 & 0 & 0 & 0 & R_r \end{bmatrix} \quad (7)$$

In above matrices, v_x , [x=a,b,c] represents stator per phase voltage and v_X , [X=A,B,C] represents per phase rotor voltage. Also, R_s and R_r are the per phase stator and rotor resistances, respectively. It should be noted that for a squirrel cage induction machine, the rotor voltages will be zero.

The electromagnetic torque (T_{em}) is as follows:

$$T_{em} = 0.5 \mathbf{I}^T \frac{d\mathbf{L}}{d\theta_{mech}} \mathbf{I} = 0.5 \frac{p}{2} \mathbf{I}^T \frac{d\mathbf{L}}{d\theta_m} \mathbf{I} \quad (8)$$

where θ_{mech} is the mechanical angle between the stator a-axis and rotor A-axis and p is the number of poles in the stator. For a 2 pole machine, the mechanical angle θ_{mech} equals the electrical angle θ_m .

Finally, the mechanical equation relating the electromagnetic torque to load torque (T_L) is given below

$$T_{em} = T_L + J \frac{d\omega_{mech}}{dt} \quad (9)$$

where J is the inertia of the machine and mechanical load and ω_{mech} is the mechanical speed of the rotor. Equations above allow modeling an induction machine.

These equations are used to create a MATLAB function file EX2_2.m to simulate the startup at no-load of an induction machine with parameters given in Table 1. The MATLAB file EX2_2.m uses the function file EX2_2function.m and generates the simulation results for the start up as shown in Fig. 1. Run the file EX2_2.m to get the following results.




Fig. 1 Simulation results for no-load startup of induction machine (a) Stator currents vs time (b) Rotor speed vs electromagnetic torque (c) Electromagnetic torque vs time (d) Speed vs time (e) Rotor currents vs time